

From: Caplan.Robert@epamail.epa.gov
To: [Pat Genzler;](#)
cc: [David Jackson;](#) [Kevin Hennessy;](#)
Subject: Clarification of Mr. Joel's affidavit
Date: Monday, October 19, 2009 4:48:10 PM

We are in the process of reviewing the 114 responses submitted by Quality and Marco. For now, we'd like some clarification of Rony Joel's affidavit.

He stated that he was informed "that the material I saw being crushed at the site was actually fiberglass reinforced concrete pipe, which I have been told looks similar to asbestos-cement pipe," and further, that it was explained to him that ". . . the fiberglass reinforced concrete pipe was being used as small-diameter storm drain pipe that was removed due to conflicts with the new drainage system."

1. Is Mr. Joel saying that the fiberglass piping was new piping installed by Quality as part of the Collier project but was then taken out of the ground where it was interfering with a new drainage system, or was it old, existing piping that was excavated by Quality?
2. Was the new drainage system different from the new sewer system?
3. How much fiberglass piping (linear feet) was installed and/or excavated by Quality?
4. Was this fiberglass piping Mr. Joel refers to in addition to, or different from the piping that you referenced in your chart showing approximately 184 linear feet of piping excavated during the project?
5. What size (lengths, diameter) was the fiberglass piping? Also, can you submit pictures of the fiberglass piping and the asbestos piping?

Thanks,

Bob

Robert Caplan, Senior Attorney
U.S. Environmental Protection Agency
Sam Nunn Federal Building - 13th Fl.
61 Forsyth Street
Atlanta, Ga. 30303
404-562-9520 (ph)
404-562-9486 (fax)

email: caplan.robert@epa.gov